




HANDMADE IN FLORENCE

TECHNICAL BULLETIN #37


June 6, 2008

MODEL/S AFFECTED: SWIFT grinder - ALL from June 2008
(serial no. 3563-1/110V and 2690-2/220V)

DESCRIPTION: Inspection hole and cover, for ease of cleaning without removing tower.



5.314 Inspection hole cover



5.372.5 Clean out tool